	SSM70258
Models	Range Rover Evoque / L538 Range Rover (All New) / L405
Title	Q355 Software Update
Category	Driveline
Last modified	06-Dec-2013 00:00:00
Symptom	501000 Automatic Transmission Concerns
Content	<u>Issue:</u> When carrying out Q355 there is potential of a software download failure on the initial attempt. <u>Cause:</u> An unknown communication concern. <u>Action:</u> Once the GSM has been re-flashed, the GSM may fail to rise following this re-flash. 1. Please re-run the application on a second attempt. 2. An ignition cycle will then need to be performed to initiate the new software.