

Reference SSM62217

XK / X150

Models XJ / X351

XF / X250

Title Loose battery terminals.

Category Electrical

Last modified 10-Jan-2013 00:00:00

Symptom 203000 Basic Electrical

Issue:

Loose battery terminals reported both by customer and Road Side Assistance personel.

Symptom will be battery charge light on.

Cause:

Reports have been received from the customer where the battery terminal has become loose /adrift causing significant electrical concerns.

The battery terminal has been incorrectly fitted or
Content with the incorrect torque applied during the PDI process or whilst the vehicle is in the workshop for repair.

Action:

To ensure that the battery terminal is located correctly, please refer to relevant TOPIX section.

TOPIX – Workshop Manual - 1.General information – 101. Pre-delivery information – Description and operation – preliminary – 4.2 Remove the transit relay.