



Update Prior to Sale Notice UPS2613: Charge Air Cooler Clip / Hose Inspection - Update

SERVICE BULLETIN

10-MAY-13

No.: 6-201NAS
[issue 2]

Section: GENERAL
INFORMATION

Market: CAN / USA

CHANGES ARE HIGHLIGHTED IN GRAY

DESCRIPTION

To confirm the as-built condition of 2013 model year XF vehicles fitted with the 2.0L GTDi engine only, inspection of the Charge Air Cooler clips and hoses is necessary. Accurate Warranty claim data is required for investigation purposes. The correct Option Code which corresponds to the vehicle condition must be claimed.

AFFECTED VEHICLES

The VIN range of affected vehicles is S51675-S92680.

WORKSHOP PROCEDURES

Retailers are required to check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Refer to Technical Bulletin UPS2613-2bNAS, *Update Prior to Sale: Charge Air Cooler Clip / Hose Inspection*, for detailed repair instructions.

PARTS

No parts required

TOOLS

Refer to Workshop Manual / Repair Procedure for any required special tools

WARRANTY

NOTE: Always check DDW to verify that the vehicle is affected by this Action prior to undertaking any repairs. Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to Repair Times Searcher (RTS) on TOPIx to obtain the latest repair time.

Warranty claims must be submitted quoting Program Code '**K178**' together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken. This program is valid for a limited time only. Warranty claims with a repair date prior to the **03 November 2013** closure date must be submitted for payment within 30 calendar days of completion of the repair.

NOTE: Accurate Warranty claim data is required for investigation purposes. The correct Option Code which corresponds to the vehicle condition must be claimed.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART No.	QTY. / VALUE
K178	B	Clip is in correct position – tighten clip	10.10.99	0.20	-	-
		Drive in/drive out	10.10.10	0.10	-	-
K178	C	Incorrect position of clip – reposition clip and tighten	05.10.20	0.20	-	-
		Drive in/drive out	10.10.10	0.10	-	-
K178	D	Incorrect position of the hose – reposition hose and clip and tighten	18.91.51	0.20	-	-
		Drive in/drive out	10.10.10	0.10	-	-

Normal Warranty policies and procedures apply