

Update Prior to Sale Notice UPS3013: Instrument Cluster Software Update

SERVICE BULLETIN

02-JUL-13

No.: 6-204NAS

Section: GENERAL INFORMATION

Market: CAN / USA

DESCRIPTION

On a limited number of 2014 model year Jaguar F-TYPE vehicles, the date format on the Touch Screen (TS) System Settings / Clock Adjust menu may be unable to be changed from 'DD/MM/YYYY' to 'MM/DD/YYYY' due to a software issue within the Instrument Cluster (IC).

△ **NOTE:** The date will only be displayed when accessing the Touch Screen (TS) Systems Settings / Clock Adjust menu.

AFFECTED VEHICLES

The VIN range of affected vehicles is K00317-K00734.

WORKSHOP PROCEDURES

Retailers are required to check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Refer to Technical Bulletin UPS3013-1bNAS, *Update Prior to Sale: Instrument Cluster Software Update*, for detailed repair instructions.

PARTS

No parts required

TOOLS

Refer to Workshop Manual / Repair Procedure for any required special tools

WARRANTY

△ **NOTE:** Always check DDW to verify that the vehicle is affected by this program prior to undertaking any repairs. Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to Repair Times Searcher (RTS) on TOPIx to obtain the latest repair time.

Warranty claims must be submitted quoting Program Code '**K181**' together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **14 December 2013** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART No.	QTY. / VALUE
K181	B	Configure existing Instrument cluster	86.99.72	0.30	-	-
K181	C	Configure existing Instrument cluster	86.99.72	0.30	-	-
		Drive in/drive out	10.10.10	0.10	-	-

Normal Warranty policies and procedures apply