GPOP - Issue Review System

Part Number: 68039341A\$, 68060741A\$

Part Description: Column Shift Cable

Issue For 2010 model year and newer, the BTSI solenoid is part of the bracket assembly Description: that mounts to the steering column. Common solenoid and bracket assy part numbers are 05057506AD and 05057507AB. Please check your part for correct

application. (Prior to 2010, the solenoid was part of the shift cable.)

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.