

GROUP: Electrical

DATE: March 22, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL 13-019 ALL APPLICABLE SOLD AND UN-SOLD VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Cluster Displays Are Incorrect

OVERVIEW:

This Bulletin involves replacing the Instrument Panel Cluster (IPC).

MODELS:

2013 (DS)

Ram 1500 Pickup (Canadian only)

NOTE: This bulletin applies to vehicles built between August 20, 2012 (MDH 0820XX) and September 12, 2012 (MDH 0912XX).

SYMPTOM/CONDITION:

A customer may experience the cluster displays are incorrect. Replacement of the cluster will correct this condition.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1 (AR)	56046541AF	Cluster

NOTE: The replacement cluster will be ordered through the exchange center, new cluster will be sent back to the dealer. The exchange center has a list of the VIN numbers for this RRT. When ordering the cluster put the RRT number under comments.

REPAIR PROCEDURE:

1. Replace the cluster, follow the procedure in TechCONNECT08 - Electrical/8J - Instrument Cluster/Removal/Installation.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
08-45-10-94	Module, Instrument Panel Cluster (IPC), Replace (0 - Introduction)	0.3 Hrs.

FAILURE CODE:

ZZ Service Action
