

9002820 01/16/2013 MY13 JS

GPOP - Issue Review System

Part Number: 68027057AA

Part Description: Convertible Top Tonneau Cover Motor Assembly

Issue Description: Prior to replacing this part, please remove the trim on the decklid and ensure the connection on the back of motor is fully seated by performing a push/pull test. If not fully seated, please engage the connection, then retest the convertible top function.

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.