## 9003761 07/26/2017 MY17 KL, RT, VF

## **GPOP - Issue Review System**

## **Part Number:** 68105838A\$

## Part Description: PCV Hose

Issue MIL Lamp On, possible P2173 and/ or P0507 Faults Due to a split or cut PCV hose.
Description: Please check for a split or cut PCV hose when the following faults are present P2173, P0507. If the PCV hose is found to be split or cut call the following FCA employee (Joe Lovell (734) 309-6467, joe.lovell@fcagroup.com). If a response is not received within 15 mins, then proceed with the necessary repair.

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.