

Technical Service Bulletin



01 MIL on (DTC P1196/P1197/P0135, heater circuit fault lambda sensor) - Repair Authorization

01 13 90 2033767/1 May 2, 2013.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6/A7, S4, S5, S5 Cabrio, Q7	2010-2012	All	3.0 FSI Engine
Q5	2010-2012	All	3.2 FSI AVS engine

Condition

- MIL on.
- One of the following DTCs is stored in the engine control module (ECM), J623 (address word 01):
 - **DTC P1196(00)** (Fault for Lambda Sensor Heater Circuit)
 - **DTC P1197(00)** (Fault for Lambda Sensor Heater Circuit)
 - **DTC P0135(00)** (Fault for Lambda Sensor Heater Circuit)

Technical Background

Not applicable.

Production Solution

No changes in production have been made, as no issues have been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

1. Verify that one of the following DTCs is stored in the ECM: **DTC P1196(00)**, **DTC P1197(00)**, or **DTC P0135(00)**.
2. Contact a TAC consultant before proceeding. Do **not** delete the DTCs.
3. Attach the DTC and diagnostic log to the TAC ticket.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Technical Service Bulletin



Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.