

Reference	SSM64657
Models	XK / X150 XJ / X351 XF / X250
Title	5.0L V8 (AJ133) water pump improvement VINS
Category	Engine
Last modified	16-Apr-2013 00:00:00
Symptom	402000 Cooling System Concerns
Content	<p>Issue: Coolant leak from 5.0L V8 (AJ133) water pump.</p> <p>Cause: A number of changes to the water pumps have been made to improve product quality.</p> <p>Action: Technical Bulletin JTB00278 has been released to help with water pump diagnostics, but the bulletin does not contain closing VINS because it is applicable to all vehicles fitted with the AJ133 V8 engine.</p> <p>Below is a list of VINS that can be used to monitor the improvements to the water pumps. EPQR do not need to be submitted for water pump leaks if they are before these VINS.</p> <p>XJ - V26805, XK - B46456, XF - S30102.</p>