

SSM69238 Coolant Hose.pdf

Reference	SSM69238
Models	XF / X250
Title	XF 2.2 Diesel Coolant Pipe noise/resonance
Category	Noise Vibration
Last modified	01-Nov-2013 00:00:00
Symptom	702000 Other Noise Concerns
Content	<p><u>Issue:</u> A Customer may report a resonance type noise from the Engine area of their vehicle on 2.2D engine derivative.</p> <p><u>Cause:</u> This may be due to the coolant spacer clips being in an incorrect location on the coolant hoses.</p> <p><u>Action:</u> Please refer to the attached document that shows the correct location for the coolant spacer clips.</p> <p>Photo A shows the correct & incorrect location of the spacer clips on the hose assy. Photo B shows the hose assy fitted on a vehicle, detailing where the correct location for the spacer clip should be.</p>