

Technical Journal

TITLE:

Vibrations in steering wheel above 60 mph

| | | | |
|--|---|--|-----------------------------------|
| REF NO: TJ 36424.1.0 | ISSUING DEPARTMENT: Technical Service | CAR MARKET: United States and Canada | |
| PARTNER: 3 US 7510 Volvo Car USA | | ISSUE DATE: 2022-12-13 | STATUS DATE: 2023-01-10 |
| FUNC GROUP: 4000 | FUNC DESC: Power transmission | Page 1 of 2 | |

“Right first time in Time”

DESCRIPTION:

If vibration occurs in the steering wheel mostly noticeable in speeds over 60mph, please follow advice under “Service”.

CSC Customer Symptom Codes

| Code | Description |
|------|---|
| 40 | Steering/Vibrations in the steering wheel |
| V7 | Complete vehicle/Vibration/When driving above 45 MPH |
| V2 | Steering wheel/Vibration/shimmy/When driving above 45 mph |
| V1 | Tires/Vibration/out of round |

DTC Diagnostic Trouble Codes

Vehicle Type

| Type | Eng | Eng Desc | Sales | Body | Gear | Steer | Model Year | Plant | Chassis range | Struc Week Range |
|------|-----|----------|-------|------|------|-------|------------|-------|---------------|------------------|
| 536 | ED | E400V6 | | | | | 2020-9999 | | - | 202037-999952 |
| 539 | ED | E400V6 | | | | | 2022-9999 | | - | 202139-999952 |

Technical Journal 36424.1.0

SERVICE:

Please start by following TJ 32161 to first exclude that the vibrations do not emanate from the wheels or wheel alignment.

If the issue still occurs after the above has been ruled out, do not replace any parts or perform further diagnosis. Analysis is ongoing to understand this concern.

This TJ will be updated when more information becomes available.

Warranty claim info:

No warranty claim accepted for a job described in this TJ, but released as information only.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 4000.