## SERVICE BULLETIN

APPLICABILITY: 2002MY Impreza WRX SUBJECT: Fuel Smell in Cold Weather NUMBER: 09-36-03R DATE: 04/01/03 REVISED: 02/19/2013

**NOTE:** Service Bulletin 09-36-03 (Fuel Smell in Cold Weather) has been deleted from STIS and has been replaced with Service Bulletin 01-170-09 (Engine Fuel Line Extended Warranty Program).

If you have copies of 09-36-03 please discard and refer to 01-170-09 for the latest parts and repair information.

Continued...

## CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

## SUBARU OF AMERICA, INC. IS "ISO 14001 COMPLIANT"

The international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.



QUALITY DRIVEN® SERVICE

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.		
---	--	--

ATTENTION:

GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER