John Frooshani

Safety Activities Manager, Government Relations

Direct Dial: (443) 430-3619 Fax: (856) 488-8669

E-mail: jfrooshani@subaru.com

September 4, 2013 Ref. No.: GR13-064

Mr. Greg Magno, Chief

National Highway Traffic Safety Administration

Defects Assessment Division (NVS-211) 1200 New Jersey Avenue, SE, Room W48-334 Washington, DC 20590

Dear Mr. Magno:

Pursuant to 49 CFR 579.5, Fuji Heavy Industries U.S.A., Inc. furnishes the following copies of communications distributed by Subaru of America, Inc. during the month of August 2013.

8-1-13 WQJ46 Recall Annoucement.pdf 8-1-13 WQJ46 Recall Campaign Bulletin.pdf 8-5-13 TSB Deletion of Compass Mirror.pdf 8-5-13 TSB ETC Mounting Guidelines 2.pdf 8-5-13 TSB Windshield Repair Areas.pdf 8-6-13 New Battery Announcement.pdf 8-7-13 TSB Design Change Cap for Oil Pressure Switch.pdf 8-7-13 TSB Windshield Repair Areas.pdf 8-8-13 TSB ETC Mounting Guidelines.pdf 8-8-13 TSB Reprogramming Bluetooth.pdf 8-9-13 TSB 12MY Exchange Comp Indentification.pdf 8-9-13 TSB 13MY Exchange Comp Indentification.pdf 8-9-13 TSB 14MY Exchange Comp Indentification.pdf 8-9-13 TSB Oil Seepage Auto Timing Belt Tensioner.pdf 8-12-13 TSB ECM Repro Cruise Control.pdf 8-12-13 TSB ECM Reprog Extended Crank.pdf 8-14-13 Return of F10 SD Card Audio-Navi.pdf 8-15-13 Position Statement.pdf 8-19-13 Service Manual Corrections.pdf 8-19-13 TSB Tire Tread Change.pdf 8-19-13 Waranty Audio-Navi Exchange Program.pdf 8-21-13 WQH44 Floor Mat Info.pdf 8-23-13 Catalytic Converter Returns.pdf 8-26-13 TSB F10 SD Card Audio-Navi.pdf 8-27-13 Labor Time Changes.pdf 8-29-13 Info Catalytic Converter Returns.pdf 8-2013 TechTips.pdf

The above documentation is provided to you in the enclosed CD. Please advise if you require hard copies of this information to Jill Ann DiVone, jdivone@subaru.com or 856-488-8637.

If you have any questions, please do not hesitate to contact me at (443) 430-3619.

Sincerely.

John Frooshani

Safety Activities Manager, Government Relations

cc: FHI - QA, CD enclosed