John Frooshani Safety Activities Manager, Government Relations

Direct Dial: (443) 430-3619 E-mail: jfrooshani@subaru.com



Fuji Heavy Industries U.S.A., Inc. c/o Subaru of America PO Box 6000 Cherry Hill, NJ 08034-6000 856-488-8500

January 7, 2013 Ref. No.: GR14- 001

Mr. Greg Magno, Chief

National Highway Traffic Safety Administration

Defects Assessment Division (NVS-211)

1200 New Jersey Avenue, SE, Room W48-334

Washington, DC 20590

Dear Mr. Magno:

Pursuant to 49 CFR 579.5, Fuji Heavy Industries U.S.A., Inc. furnishes the following copies of communications distributed by Subaru of America, Inc. during the month of December 2013.

12-3-13 TSB-R Surface Treatment Change Oil Control Piston Rings.pdf

12-3-13 TSB-R Surface Treatment Change Oil Control Piston Rings-2.pdf

12-4-13 2014 XVCrosstrek HYBRID.pdf

12-4-13 Multipoint Inspection Form.pdf

12-9-13 Bulletin Hybrid Battery.pdf

12-10-13 Special Quality Team Activity.pdf

12-11-13 Special Service Tools Website.pdf

12-11-13 TSB-R Cust Satisfaction Navi SD Card Update.pdf

12-13-13 Battery Tester Info.pdf

12-16-13 Reminder Navi Update.pdf

12-17-13 TSB Revolution Sensor O Ring.pdf

12-18-13 TSB CVT Comp Design Changes.pdf

12-18-13 XV Crosstrek Interview Check Sheet.pdf

12-20-13 High Voltage Insulation-Leather Protection Gloves.pdf

12-20-13 Navi Hardware Replacement AHA Upgrade Extended.pdf

12-23-13 TSB Cracked Rear Comb Lamps.pdf

12-30-13 SD Update 13MY Legacy\_OB.pdf

12-2013 TSB-R Abnormal Sound from Engine Mounts.pdf

2013 Dec TechTIPS.pdf

The above documentation is provided to you in the enclosed CD. Please advise if you require hard copies of this information to Jill Ann DiVone, <u>jdivone@subaru.com</u> or 856-488-8637.

If you have any questions, please do not hesitate to contact me at (443) 430-3619.

Sincerely,

John Frooshani

Safety Activities Manager, Government Relations

cc: FHI - QA, CD enclosed