

Subarunet Announcement

To: SDC EST CEN WST

From: Subaru of America, Inc.

Department: Service

Date: May 22, 2013

Category: Parts/Service

Subject: WQI-45 2013MY Legacy/Outback Steering Column Service Procedure Update

NOTE: The plastic shipping insert (indicated by red arrow below) must be removed prior to installing the new steering column in the vehicle.

Page 8 of the campaign bulletin will be revised to include a note specifying removal of this plastic shipping insert. Please refer to STIS for the revised version of the campaign bulletin.

