

Technical Bulletin



Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All (except Routan)	2011-2013	All	All	All	All

Condition

40 13 01 March 20, 2013 **2033347**

CV Boot Replacement

CV boot damage identified.

Technical Background

Recommended procedure for removing damaged CV boot.

Production Solution

Not applicable.

Service

If it is determined that a CV boot needs to be replaced, the boot should be removed and replaced without cutting or slicing the boot open. Once the CV Joint is removed the boot will slide off the axle shaft. Refer to repair manual group 40, removal procedure for drive axle disassembly, in ElsaWeb.



Note:

Claims will not be accepted if the CV Boot is cut or sliced.



CV Boots should not be cut or sliced upon removal.



CV Boots should slide off the driveshaft after the removal of the CV Joint.

Warranty

Information only.

Required Parts and Tools

No Special Parts required.

No Special Tools required.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.