



Tech Tips

TT 40-13-01

Date: April 26, 2013

2012-2013 **Beetle**, CC, Eos, Golf/GTI, Jetta, Jetta Sportwagen, Passat, Tiguan – CV Boot Leaking Grease, Clamp Not Tight or Not Aligned Properly

May 3, 2013: Update to Applicability.

If a CV boot is found to be leaking grease on PDI and a clamp is found to be loose or not aligned properly, only the clamp should be replaced. If concern is found after the vehicle is sold, replace the complete CV joint.