

A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the [Elsa Newsletter](#) section in the Technician References menu.

Audi  
Truth in Engineering 

# Audi Elsa Newsletter

Edition 57: October 14, 2013

## Content

- [Breast Cancer Awareness Month](#)
- [Technical Bulletins](#)
- [Pending Service Solutions](#)
- [Campaigns](#)
- [Updates](#)
- [Suggestions](#)



## Breast Cancer Awareness Month

In honor of Breast Cancer Awareness month, the Elsa Newsletter has gone pink this week.

According to a recent report published in the American Association for Cancer Research in October 2012, approximately 232,000 women will be diagnosed with breast cancer in 2013, according to government statistics. More than 39,000 women were expected to die from the disease last year.

About eight in 10 breast cancer cases and almost nine in 10 breast cancer deaths

occur in women 50 years of age and older.

Visit the [National Breast Cancer Awareness Month](#) website for a list of organizations that accept contributions for this cause.

[Back to top](#)

## Technical Bulletins

<b>66 Wind noise from exterior rear view mirror housing at turn signal seam (2033517/2)</b>		
Model(s)	Year	Vehicle Specific Equipment
Q5	2009-2014	Not Applicable
Q7	2010-2014	Not Applicable
<b>Condition:</b> Wind noise is heard by the customer at highway speeds. <b>Production Solution:</b> Not applicable.		

<b>66 Wind noise from exterior rear view mirror base or at lane change assist lamp(2029586/6)</b>		
Model(s)	Year	Vehicle Specific Equipment
Q5	2009-2014	Not Applicable
Q7	2010-2014	Not Applicable
<b>Condition:</b> The customer may report hearing wind noise while driving at highway speeds. The noise may occur on either side of the vehicle. <b>Production Solution:</b> Improved parts have been implemented into production.		

<b>51 Vehicle inspection, protection removal, and detailing (2009967/11)</b>		
Model(s)	Year	Vehicle Specific Equipment
All	2012-2015	Not Applicable
<b>Condition:</b> Instructions for vehicle inspection, protection removal, and detailing. <b>Production Solution:</b> Not applicable.		

**74 Leather upholstery, cleaning tips (2004327/4)**

Model(s)	Year	Vehicle Specific Equipment
All	2002-2015	Leather upholstery
<b>Condition:</b> Leather upholstery is dirty or stained. <b>Production Solution:</b> No change.		

**66 Wind noise from exterior rear view mirror (2026997/3)**

Model(s)	Year	Vehicle Specific Equipment
Q5, Q7	2014	Not Applicable
<b>Condition:</b> Customer may report hearing wind noise from the front door area. After diagnosis, it is determined that the source of the wind noise is the exterior rear view mirrors. <b>Production Solution:</b> No changes to production have been made, as no issue has been identified for vehicles in the production range for which this TSB appears.		

**01 MIL on (P0300 and/or P0301- P0308, P1923)(2030478/3)**

Model(s)	Year	Vehicle Specific Equipment
R8	2011-2012	4.2 FSI Engine
<b>Condition:</b> <ul style="list-style-type: none"><li>• MIL on.</li><li>• DTC P1923 (Check DTC memory of Engine Control Module (ECM) 2) is stored in the engine control module.</li><li>• One or more DTCs for random cylinder misfires (DTC P0300 - DTC P0308) is stored in the engine control module.</li></ul> <b>Production Solution:</b> New software in the engine control modules (ECM), J623 and J624, addressed the condition.		

**66 Wind noise from exterior rear view mirror base or at lane change assist lamp (2029586/7)**

Model(s)	Year	Vehicle Specific Equipment
Q5	2009-2014	Not Applicable
Q7	2010-2014	Not Applicable

**Condition:** The customer may report hearing wind noise while driving at highway speeds. The noise may occur on either side of the vehicle.  
**Production Solution:** Improved parts have been implemented into production.

**27 Battery testing and charging - vehicles with BDM (J367)(2023282/3)**

Model(s)	Year	Vehicle Specific Equipment
A5, S5	2008-2014	Not Applicable
A4, Q5, Q7, A6	2009-2014	Not Applicable
A5, S5 Cab.	2010-2014	Not Applicable

**Condition:** Battery testing and charging for vehicles equipped with a Battery Data Manager (BDM - J367).  
**Production Solution:** Not applicable.

## Pending Service Solutions

No new pending service solutions this week.

[Back to top](#)

## Campaigns

No new campaigns this week.

[Back to top](#)

## Updates

No new updates this week.

[Back to top](#)

## Suggestions

Please send comments or suggestions to: [aoa.workshopinformation@audi.com](mailto:aoa.workshopinformation@audi.com)

[Back to top](#)

© 2013 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.