



Service Bulletin

File in Section: -

Bulletin No.: PIC5611B

Date: November, 2013

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Rear Camera Guideline Selection Is Not Available on Some Radio RPOs

Models: 2012-2013 Buick Lacrosse, Regal
2012-2014 Buick Verano
2013-2014 Buick Encore
2012-2014 Chevrolet Camaro, Cruze, Equinox, Malibu
2012-2014 GMC Terrain

This PI was superseded to update model list. Please discard PIC5611A.

Condition/Concern

Some customers may comment that the rear camera guideline selection is not available.

Recommendation/Instructions

The owner's manual does not specify that the rear camera guideline selection is only available on vehicles equipped with RPO UYS or UEW Navigation Radio. To avoid unnecessary repair attempts, please verify the vehicle has RPO UYS or UEW prior to performing any repairs. As a result, vehicles equipped with UFU, UP9, or UHQ will not have the guidelines. If equipped with UYS or UEW, verify the guideline option is turned on. This can be checked by pressing Config, Display, and then select Guidelines.