

## Service Bulletin

Bulletin No.:

n No.: PIC5927 Date: October, 2013

# **PRELIMINARY INFORMATION**

Subject: Rear Brake Noise On First Apply

#### Models: 2013 Buick Encore

2013 Chevrolet Trax (Canada)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

#### **Condition/Concern**

Customers may comment on a rear brake noise that occurs on first brake apply when backing up but can also occur in drive.

### **Recommendation/Instructions**

The correction is to install a dampener P/N 13343688 and bolt P/N 13343686 in place of the rear upper caliper mounting bolts. Refer to SI for bolt removal instructions and torque spec listed in the Brakes section under Rear Disc Brake Pads Replacement.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.