

SB-10045160-4021

Countries: CANADA, UNITED STATES, PUERTO RICO
Availability: ISIS, FleetISIS
Major System: EXHAUST
Current Language: English
Other Languages: NONE
Viewed: 241

Document ID: IK0700047
Revision: 1
Created: 6/28/2012
Last Modified: 12/10/2013
Author: Keith Kierzek

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		View My Bookmarks				10	1

Title: Horizontal Aftertreatment Mounting Bolt Torque

Applies To: ProStar, TranStar, WorkStar equipped with MF 11/13 engines

DESCRIPTION

Horizontal Aftertreatment Mounting bolt loose

SYMPTOMS

Horizontal Aftertreatment Support Rod Bolt loose or backed out of Aftertreatment Support Hanger Rod.

PARTS INFORMATION

Part #	Description	Qty.
3536430C1	bolt	As Required

TROUBLESHOOTING

1. Inspect for Support Rod Bolt to be loose or backed out of Support Rod
2. If loose inspect bolt for wear and replace if necessary

RESOLUTION

Torque Support Rod Bolt to 88-108 NM / 65-80 Ft. Lbs.

[Hide Details](#)**Feedback Information**

Viewed: 240

Helpful: 10

Not Helpful: 1

No Feedback Found

Copyright © 2014 Navistar, Inc.