

SB-10045160-7827

Countries: CANADA, UNITED STATES **Document ID:** IK0700047
Availability: ISIS, FleetISIS **Revision:** 0
Major System: EXHAUST **Created:** 6/28/2012
Current Language: English **Last Modified:** 7/6/2012
Other Languages: NONE **Author:** Jim Restemayer
Viewed: 103

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 6	 0

Title: Horizontal Aftertreatment Mounting Bolt Torque**Applies To:** ProStar, TranStar, WorkStar equipped with MF 11/13 engines**DESCRIPTION****Horizontal Aftertreatment Mounting bolt loose****SYMPTOMS**

Horizontal Aftertreatment Support Rod Bolt loose or backed out of Aftertreatment Support Hanger Rod.

PARTS INFORMATION

Part #	Description	Qty.
3536430C1	bolt	As Required

TROUBLESHOOTING

1. Inspect for Support Rod Bolt to be loose or backed out of Support Rod
2. If loose inspect bolt for wear and replace if necessary

RESOLUTION

Torque Support Rod Bolt to 88-108 NM / 65-80 Ft. Lbs.

[Hide Details](#)**Feedback Information**

Viewed: 102

Helpful: 6

Not Helpful: 0

No Feedback Found

Copyright © 2012 Navistar, Inc.