

**ABS ECU Reprogramming
VN****SP 593-011, ABS ECU Reprogramming****(February 2013)**

Certain Volvo VN Trucks built between 08/20/12 and 11/02/12, the software in the Bendix ABS module contains an incorrect setting.
To correct this issue follow the procedure below:

Required Parts

Part Number	Description
22084154	Reconfiguration RDU (Bendix Part Number K093037)

Procedure

1. To order part and instructions please call 1-866-865-1052.
2. Once programming is complete you **MUST** call 1-866-865-1052 to receive a return shipping label.

Note: Part **MUST** be returned in the same packaging as received.

Reimbursement

This repair is covered by an authorized Service Program. Reimbursement is obtained via the normal claim handling process.	
Claim Type (used only when uploading from the Dealer Bus. Sys.)	W
Recall Status	
Vehicle inspected, repair not required	1- Inspected OK
Vehicle repaired per instruction	2- Modified per instruction
Labor Code	
Primary Labor Code	59308-0-02 0.3 hrs
Causal Part	21865546
Parts Disposition	
Authorization Number	SP593-011
Expiration Date	12-February-2014

Note: Take Charge Time is not included in the Labor Code for this operation. Take charge may be eligible but can only be used once per repair visit. If vehicle is having other warranty repairs performed, take charge should be charged to the warranty repair, otherwise take charge can be charged to this service program.