



March 2013  
Special Policy Adjustment  
Bulletin SB13-04-S002

**SPECIAL POLICY ADJUSTMENT  
DRIVER DOOR SWITCH SHORT CIRCUIT**

**To:** All Isuzu, VP, and Corporate Service Staff

This letter is being sent to you to notify you of a Special Policy Adjustment – Driver Door Switch Short Circuit on certain Isuzu Ascender passenger vehicles.

**Affected Vehicles:**

- 2006-2007MY Isuzu Ascender Vehicles

**Condition:**

If fluid enters the driver's door module, it may cause a short in the circuit board. A short may cause the power door lock and power window switches to function intermittently or become inoperative. In extremely rare cases, a short may cause overheating, which could melt components of the door module, producing odor, smoke, or flame.

**Special Policy Adjustment**

If a vehicle involved in this special policy demonstrates the condition or symptoms described above, service facilities are to replace the driver door module, regardless of the vehicle's age or mileage.

**Service Facility Notification:**

SERVICE FACILITY NOTIFICATION WILL BEGIN MARCH 29, 2013

**Owner Notification:**

OWNER NOTIFICATION WILL BEGIN APRIL 5, 2013