

**SB-10051902-2550**

Reference	SSM63057
Models	Range Rover Evoque / L538
Title	Evoque 2012 onwards difficult to open doors in cold conditions
Category	Body
Last modified	09-May-2013 00:00:00
Symptom	111000 Body Panel(s)/Unibody
	<p><u>Issue:</u></p> <p>Difficult to open doors in cold temperatures as the door seal is frozen to the opening.</p> <p><u>Cause:</u></p> <p>Water collects around the door seal attached to the door and freezes in cold temperatures.</p> <p><u>Action:</u></p> <p>This concern can naturally occur with the above conditions.</p> <p>Content PEOX DF gel (30ml) and PEOX 612 paste (50 g) can help to reduce this symptom and can be sourced from the squeeks and rattle kit, part number LR037626.</p> <p><u>Use:</u></p> <ul style="list-style-type: none"> <li>• Apply thin even coats of either product to the door seals and allow to dry (the time to dry changes with temperature and humidity).</li> <li>• Warm air can be used to reduce the time to dry the product.</li> <li>• Components can be installed while PEOX is still soft, although the product does not get to full performance until fully dry.</li> </ul> <p>GDTS#</p>