

SB-10051902-2710

Reference SSM63057

Models Range Rover Evoque / L538

Title Evoque 2012 onwards difficult to open doors in cold conditions

Category Body

Last modified 12-Feb-2013 00:00:00

Symptom 111000 Body Panel(s)/Unibody

Issue:

Difficult to open doors in cold temperatures as the door seal is frozen to the opening.

Cause:

Water collects around the door seal attached to the door and freezes in cold temperatures.

Action:

Content

- This concern can naturally occur with the above conditions.
- Send an electronic Product Quality Report (ePQR) to allow engineering to understand the reported concern.
- Include photographs if possible.
- Include the ambient temperature when the incident occurred.

GDTS#