

SB-10051904-7551

Reference SSM62877

Models XF / X250

Title XF LHF Indicator Inoperative

Category Electrical

Last modified 11-Feb-2013 00:00:00

Symptom 201000 Lighting Systems

Issue:

LHF Indicator inoperative.

Cause:

Possible water ingress into lamp assy via the upper vent.

Action:

Content Should this issue be presented please continue to check the integrity of the wiring circuit and connector first. If all is correct and still the Indicator is not working and or there appears to have been water ingress at some time then replace the light assembly to rectify.

Assured parts from VIN# S72091