

Service Campaign Bulletin

Campaign No. 2013010008, February 2013

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 906, Model Year 2012**
Update Engine Control Module Software

This Service Campaign has been initiated because Daimler AG (DAG), the manufacturer of Mercedes-Benz and Freightliner Sprinter vehicles, has determined that the ADBLUE system does not correspond to internal specifications. Dealers will update the Engine Control Module software at the next workshop visit.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Please note that Recall and Service Campaigns **do not expire** and may also be performed on a vehicle with a vehicle status indicator.

Approximately 18,656 vehicles are affected.

Order No. V-SC-2013010008

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.