



Service Bulletin

File in Section: -

Bulletin No.: PIC5829

Date: March, 2013

PRELIMINARY INFORMATION

Subject: SES Light With DTC U0111

Models: 2011-2013 Chevrolet Volt

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may experience a SES lamp with a current or history code U0111.

Recommendation/Instructions

If you experience this DTC, please don't replace the Battery Energy Control Module (BECM). Update the BECM with the latest calibrations in TIS-2-Web. A new calibration has been released to address this issue.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
N9703	Reprogram Battery Energy Control Module	0.4
* This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.