


<h1>Technical Journal</h1>			
TITLE: ACC, slight speed reduction without any vehicle ahead			
REF NO: TJ 27177	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Cars North America		ISSUE DATE: YEAR MONTH DAY 2013 06 11	
FUNC GROUP: 3872	FUNC DESC: Collision avoidance	Page 1 of 2	

“Fixed Right — First Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
124							2013-2014		0165101-0177403	201220-201322
134							2013-2014	21	0170118-0273342	201220-201322
134							2013-2014	22	0170118-0272413	201220-201322
136							2013-2014		0146101-0176325	201220-201322
156							2013-2014		0365050-0504648	201046-201322

CSC Customer Symptom Codes

Code	Description
AQ	Cruise control/Does not engage
1R	Front monitoring/Active safety/Lane Departure Warning does not work
1S	Front monitoring/Active safety/Driver Alert Control does not work
1X	Front monitoring/Active safety/Adaptive cruise control does not work
IV	Text window and warning symbol/Text message

DTC Diagnostic Trouble Codes

Text

ACC = Adaptive Cruise Control

FLR = Forward Looking Radar

**DESCRIPTION:**

It may happen that the ACC slightly reduces the vehicle speed without any vehicles ahead.

PRODUCT MODIFICATION:

An improved FLR software has been introduced in production from structure week 2013w22, chassis number breakpoint above.

SERVICE:

For customer complaints of the above symptom, upgrade the FLR software.
See TJ 26288 if DTC FSM-C1A6754 and/or FSM-C1A6768 are present.

VSTG OPERATION NUMBER:

36004-2: Software control module downloading, see VSTG.