

VEHICLE QUARANTINE NOTICE		
To:	All Dealers in Appendix A, Distribution Centres	Reference QN-07-0016 Issued: 30 April 2013
For the attention of:	Service Manager/After Sales Manager	
Please copy to:	The Dealer Principal	
	The Service Manager	
	The Sales Manager	
	The Warranty Administrator	
	Aston Martin Technician(s)	
	The Parts Manager	
Model:	Vanquish and DB9 14MY, Auto Transmission only	
VIN Range:	Refer to Appendix A	
Subject:	Incorrect Oil Level for the Differential	Page 1 of 4

Reason for this Quarantine Notice

A problem occurred with the equipment that fills the differential units with oil, during production. This means that it is possible that a small quantity of Vanquish and DB9 have an incorrect quantity of oil in the differential unit. Please refer to the list of VINs in Appendix A of this Quarantine Notice and do the Workshop Procedure that follows to all of the vehicles in the list.

IMPORTANT!

DO NOT LET THE VEHICLE LEAVE YOUR WORKSHOPS UNTIL THIS QUARANTINE WORK IS COMPLETED.

Contents of this Document

This Quarantine Notice has the parts that follow:

- Workshop Procedure
- Appendix A - List of Applicable VINs.

Please refer to Appendix A for the list of applicable VINs of the vehicles that are affected by this Quarantine Notice.

Workshop Procedure

WARNING: THE OIL IN THE DIFFERENTIAL WILL BE HOT AFTER OPERATION. LET THE OIL COOL BEFORE YOU DO WORK. IF YOU DO NOT, PERSONAL INJURY CAN OCCUR.

WARNING: THE OIL IN THE DIFFERENTIAL CAN BE HARMFUL. OBEY THE DIFFERENTIAL OIL MANUFACTURER'S SAFETY INSTRUCTIONS WHEN YOU DRAIN AND FILL THE DIFFERENTIAL.

1. If you need to add oil during the step that follows, record the quantity of oil that added.
2. Do a check of the oil level in the differential and fill if necessary (refer to Workshop Manual procedure 07.01.CF).

3. Send an email to AMTech. For the subject of the email, please type: "FAO Steve Tiltman, QN-07-0016". In the email, tell us:
- The VIN number of the vehicle
 - The quantity of oil that you added to the differential.

Warranty Data

Description	Labour Time	Repair Operation Code
Do a check of the differential oil level and fill if necessary.	DB9 - 0.4hours Vanquish - 0.4 hours	07.01.CF

Part Data

Not applicable

If you have any questions about this Quarantine Notice, please contact: Steve Tiltman at Aston Martin After Sales Operations on: +44 (0) 1926 644700 or facsimile: +44 (0) 1926 644733.
E-mail: amtech@astonmartin.com. Or contact your After Sales Manager.

The English version of this Quarantine Notice is written in Simplified Technical English to ASD-STE100™

Appendix A – List of Applicable VINs

Country	Dealer Name	Model	VIN
Australia	Trivett Classic Melbourne	Vanquish	J00711
Australia	Trivett Classic Sydney	Vanquish	J00715
Belgium	Aston Martin Brussels	Vanquish	J00727
Canada	Aston Martin Vancouver	DB9	A15134
Canada	Decarie Motors	Vanquish	J00718
China	Aston Martin Chengdu	DB9	A15138
China	Aston Martin Chengdu	DB9	A15146
Germany	Sixt Germany	DB9	B15130
Germany	Sixt Germany	DB9	B15131
Japan	Aston Martin Akasaka	Vanquish	J00712
Poland	Aston Martin Warszawa	Vanquish	J00730
Qatar	Horizon Automobiles	Vanquish	J00720
Switzerland	Aston Martin Geneva	DB9	B15133
UK	AML UK Press & Marketing	Vanquish	J00717
UK	Aston Martin Works Newport Pagnell	DB9	B15172
UK	Business Partner	DB9	B15145
UK	Harwoods	DB9	A15163
UK	Harwoods	DB9	B15152
UK	HWM	DB9	B15156
UK	JCT 600	DB9	B15175
UK	Lancaster Sevenoaks	DB9	A15165
UK	Stratstone Amersham	DB9	B15154
UK	Stratstone Derby	DB9	A15144
UK	Stratstone Hagley	DB9	B15164
UK	Stratstone Mayfair	Vanquish	J00722
UK	Stratstone Tyne and Wear	DB9	A15132
UK	Stratstone Tyne and Wear	DB9	B15170
USA	Aston Martin Beverly Hills	DB9	A15155
USA	Aston Martin Beverly Hills	DB9	A15160
USA	Aston Martin Dallas	DB9	B15166
USA	Aston Martin New England	DB9	A15157
USA	Aston Martin Newport Beach	DB9	A15162
USA	Aston Martin Newport Beach	DB9	A15169
USA	Aston Martin of Tampa	DB9	A15136
USA	Aston Martin of Tampa	DB9	A15178
USA	Aston Martin of Tampa	DB9	B15159
USA	Aston Martin of Tampa	Vanquish	J00726

Country	Dealer Name	Model	VIN
USA	Aston Martin Stock US – West	Vanquish	J00724
USA	Galpin Aston Martin	DB9	A15171
USA	Star Motor Cars	DB9	A15173
USA	Star Motor Cars	Vanquish	J00716