



Service Bulletin

File in Section: -

Bulletin No.: PIC5837

Date: June, 2013

PRELIMINARY INFORMATION

Subject: Diagnostic Aid - Service Stability Message, ABS MIL With C0800 SYM07

Models: 2013 Buick LaCrosse
2013 Buick Regal
2013 Chevrolet Malibu

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer or technician may indicate the ABS MIL is illuminated and there is a "Service Stability" message displayed. DTC C0800 Symptom 07 is set along with any wheel speed sensor: DTC C0035, C0040, C0045 or C0050.

Recommendation/Instructions

Note: Do NOT replace the EBCM for DTC C0800.

The technician should diagnose and repair any wheel speed sensor fault "before" addressing DTC C0800.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.