

[Next Unread Message](#)**View Message**

Sent on 06 05 2013 **Expires on** 06 19 2013
From Parts and Service Division
Subject Request for Visit: 2013 V6 Accord Rear Head Cover Gasket Leaks

To: All Honda Service Managers/Advisors
From: Technical Research & Support Group
Re: Request for Visit: 2013 V6 Accord Rear Head Cover Gasket Leaks

Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

Background

American Honda (AHM) is investigating certain 2013 V6 Accords with an oil leak at the rear head cover gasket. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifier

AHM is interested ONLY if the vehicle meets the following requirement:

1. Vehicle must be under the New Vehicle Limited Warranty (3 years or 36,000 miles).
2. Both 2 door and 4 door are okay.
3. Leak must be from the V6 rear head cover gasket.
4. No previous rear head cover removal.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2013, American Honda Motor Co., Inc. All Rights Reserved.