

SB-10052818-1816

Countries:	CANADA, UNITED STATES	Document ID:	IK1600183
Availability:	ISIS, FleetISIS	Revision:	2
Major System:	CAB / SLEEPER / HOOD	Created:	5/9/2013
Current Language:	English	Last Modified:	8/6/2013
Other Languages:	NONE	Author:	Jim Restemayer
Viewed:	828		

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 7	 0

Title: Offensive Odors Inside Cabin**Applies To: Post 2010 ProStar TranStar****DESCRIPTION**

Driver complaint of offensive odors in the cab.

TOOLS REQUIRED

General hand tools
1/4 inch drill bit
Drill

PARTS INFORMATION

Cowl Tray Kit : P/N 2511806C91

REPAIR PROCEDURE

Click on the following items:

[Diagnostic Flow Chart](#)

[Cowl Tray Installation Instructions.docx.pdf](#)

OTHER RESOURCES

Click on the following items:

[Exhaust Leak Troubleshooting for 2007](#)

[Exhaust Leak Troubleshooting for 2010 Emission](#)

[PDOC Clamp](#)

Click Here for: [Exhaust Manifold Ring Seal Removal / Installation](#)

Click Here for: [Exhaust Manifold Gasket Removal and Installation Procedure](#)

 Hide Details

Feedback Information

Viewed: 827

Helpful: 7

Not Helpful: 0

No Feedback Found

Copyright © 2013 Navistar, Inc.