



# Service Bulletin

File in Section: 05 - Brakes  
 Bulletin No.: 09-05-22-005C  
 Date: August, 2013

## TECHNICAL

**Subject:** Slight Brake Fluid Leak/Weeping Around Master Cylinder Reservoir Cap  
 (Replace Cap and Reservoir)

**Models:** 2010-2013 Chevrolet Camaro

This bulletin has been revised to add the 2012-2013 model years, brake fluid reservoir replacement, update the Parts Information and update the Labor Operation to the Global Labor Code (GLC). Please discard Corporate Bulletin Number 09-05-22-005B.

### Condition

Some customers may comment that brake fluid is seeping from the master cylinder reservoir cap.

### Correction

**Important:** Do Not Replace the master cylinder assembly to correct this condition.  
 Replace the reservoir and cap with the parts listed below. Refer to Master Cylinder Reservoir Replacement in SI.

### Parts Information

Part Number	Description	Quantity
22956543	Brake Master Cylinder Reservoir Kit	1
22795538	Brake Master Cylinder Reservoir Cap	1

### Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2440030	Master Cylinder Reservoir Replacement	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY  
 TECHNICIAN  
 CERTIFICATION**