

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR JUNE 2013**

32258 2013 C-MAX/Fusion Energi With DTCs P0D08 And/or P0D0F

Some 2013 C-MAX and Fusion Energi vehicles may set DTC P0D08 and/or DTC P0D0F and experience no charging. 1) CLEAR the BECM and SOBDM DTCs. 2) Connect to a 120 or 240 volt EVSE. 3) Observe the CPLR for 2 minutes and verify the vehicle is charging. Repeat two more times. 3) Perform self-test on the BECM. If P0D08 or P0D0F return, refer to the workshop manual pinpont tests. If P0D08 or P0D0f do not return, do not perform any additional service actions. A software revision is under development. Monitor OASIS for updates.