

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR JUNE 2013**

32283 2013 Police Utility Tire Pressure Monitoring System (TPMS) Lamp On

Some 2013-2014 Police Utility units may exhibit a Tire Pressure Monitor System (TPMS) lamp on and/or one or more tire sensors that won't program. This may be due to electrical interference caused by the add-on police radios and equipment. The TPMS module is located at the base of the center stack on units with the steel console mounting plate, and under the center console on units with the interior upgrade package. Please refer to Police Interceptor Modifier Bulletin P018 which can be found under the 2013 Police Modifiers Guide selection on the Ford Fleet website for information regarding relocating and shielding the module to reduce signal interference. Changes to the vehicle to reduce interference caused by add-on equipment are not warrantable.