

SP 3-820-001
SERVICE PROGRAM

October, 2013

ATTENTION:

Service Managers / Parts Managers

SUBJECT:

Xpeditor Starter Spacer Installation.

DESCRIPTION OF WORK:

This Service Program provides information regarding the installation of a starter spacer.

PROGRAM EXPIRES:

October 31, 2014

VEHICLES AFFECTED:

This Service Program covers vehicles manufactured with serial numbers ranging from 210941 through 215411. Refer to the VIN list beginning on page 5.

SERVICE RESPONSIBILITY:

Service Programs are performed on eligible vehicles at no charge to the owner until the expiration date listed above.

SERVICE PROGRAM INFORMATION:

Service Programs are product modifications and/or product improvements that Autocar has determined will enhance the operation of the truck. In a continuing effort to inform our customers of potential service issues and avoid unnecessary down time, Autocar has identified the following operation as recommended preventive maintenance.

This Service Program should be added to your preventive maintenance and service manuals.

While being committed to continuous product improvement, Autocar is not liable for updating existing chassis after they have been placed in service.

Questions regarding this Service Program should be directed to Autocar Technical Support at 888-218-3611.

TO OBTAIN PARTS:

Ensure that you have authorization from the customer to perform this work, and send an e-mail to:

warranty@autocartruck.com

Include:

1. VIN(s) (or) (last 6 digits of the VIN(s))
2. Attention To Name
3. Ship To Address.

SP 3-820-001

SERVICE PROGRAM

October, 2013

REQUIRED PARTS:

- S8200002K001-Kit, starter spacer
- (3) GM042012AA18 Bolt
- (1) S8200001-001 Starter spacer

CLAIMS FOR REIMBURSEMENT:

Order parts and submit a claim for reimbursement in accordance with Autocar's Warranty Administration Manual.

CLAIM CODING INFORMATION:

Repair Number (Op Code)	Time Allowance (SRT)	Description
33102-0-04	0.90 HR	Starter Spacer Installation

TOOLS REQUIRED:

- 3/8" drive ratchet
- 3/8" drive 12 point 12 MM socket
- 3/8" drive 10" extension
- 3/8" drive Torque wrench (55 Ft-lbs)



WARNING

Allow the vehicle's engine and cooling system to cool to ambient temperature before performing the repair procedure. A hot engine or cooling assembly may cause burns or other personal injury.



WARNING

To prevent eye injury, always wear eye protection when performing vehicle maintenance, service or inspection.



WARNING

Before working on a vehicle, set the parking brake, place the transmission in neutral and block the wheels. Failure to do so can result in unexpected vehicle movement and can cause serious personal injury or death.

SP 3-820-001

SERVICE PROGRAM

October, 2013

SAFETY NOTICES



CAUTION

LOCKOUT/TAGOUT PROCEDURES

Before entering the vehicle or vehicle body, read and follow OSHA regulations concerning entry and working in "CONFINED SPACE" OSHA 1910.146 and "LOCKOUT/TAGOUT" OSHA 1910.147. Follow OSHA regulations while performing any work on the vehicle. The vehicle must be disabled by the following steps before performing any work on the vehicle:

1. Place the transmission in NEUTRAL.
2. Set the parking brake.
3. Shut the engine OFF.
4. Lock cab doors, keep the key in your pocket. Block the wheels before entering the body or performing any work on the vehicle.
5. Turn the battery disconnect switch OFF, if equipped.
6. Completely drain the air from the primary/A system and secondary/B system by opening the drain valves on the air tanks themselves or by using the drain manifold if supplied. When draining the air tanks, do not look into the area where air is draining. Dirt or sludge particles may be expelled in the air stream and can cause eye injury.
7. Place magnetic "DANGER" signs on both cab doors before entering the body or performing any work on the vehicle.
8. Take proper precautions before working under the vehicle. Use ramps approved for the weight of your vehicle, or use floor jacks and stands. Never work under a vehicle supported by jacks alone. Always use jack stands to support the vehicle.



WARNING

Autocar natural gas powered vehicles require specific compliance in the service, storage and refueling procedures.

If you store or dispense Compressed Natural Gas (CNG) or Liquid Natural Gas (LNG), or if you work on CNG or LNG trucks, your location must be fully compliant with applicable codes, regulations and standards, including National Fire Protection Association (NFPA) codes, Society of Automotive Engineers (SAE) standards, American National Standards Institute (ANSI), Natural Gas Vehicle (NGV) standards, the United States Code of Federal Regulations (CFR), and your state and local fire and other applicable codes (including the California Code of Regulations and the Texas Administrative Code, as applicable).

Contact your local fire department for guidance and additional compliance information. Technicians working on Autocar trucks with CNG or LNG engines must be trained in the proper repair of CNG and LNG engines and the safe storage and dispensing of CNG and LNG.

SP 3-820-001

SERVICE PROGRAM

October, 2013

INSTALLATION OF STARTER SPACER

1. Locate the starter (see Figure 1).
2. Remove the three bolts and discard.
3. Remove the starter (see Figure 1).
4. From the service kit (S8200002K001), install the starter spacer (S820001-001) (see Figure 1).
5. From the service kit (S8200002K001), install the three bolts (GM042012AA18) and tighten to 55 ft-lbs (74 N·m) of torque (see Figure 1).
6. Check starter operation by starting the engine.
7. Installation of starter spacer is complete.




Figure 1

SP 3-820-001
SERVICE PROGRAM

October, 2013

5VCACL8F8AH210941	5VCACD8F3AH211078	5VCACD8F9AH211294	5VCACD8F3AH211405
5VCACS8F7AH210942	5VCACD8F5AH211079	5VCACD8F0AH211295	5VCACD8F5AH211406
5VCACS8F9AH210943	5VCACD8F1AH211080	5VCACD8F2AH211296	5VCACD8F7AH211407
5VCACL8F8AH211037	5VCACD8F3AH211081	5VCACD8F4AH211297	5VCACD8F9AH211408
5VCACL8FXAH211038	5VCACD8F5AH211082	5VCACD8F6AH211298	5VCACD8F0AH211409
5VCACL8F1AH211039	5VCACD8F7AH211083	5VCACD8F8AH211299	5VCACD8F7AH211410
5VCACL8F8AH211040	5VCACD8F9AH211084	5VCACD8F0AH211300	5VCACD8F9AH211411
5VCACL8FXAH211041	5VCACD8F0AH211085	5VCACD8F2AH211301	5VCACD8F0AH211412
5VCACL8F1AH211042	5VCACD8F2AH211086	5VCACD8F4AH211302	5VCACD8F2AH211413
5VCACL8F3AH211043	5VCACD8F4AH211087	5VCACD8F6AH211303	5VCACD8F4AH211414
5VCACL8F5AH211044	5VCACD8F6AH211088	5VCACD8F8AH211304	5VCACD8F6AH211415
5VCACL8F7AH211045	5VCACD8F8AH211089	5VCACD8FXAH211305	5VCACD8F8AH211416
5VCACL8F9AH211046	5VCACD8F4AH211090	5VCACD8F1AH211306	5VCACD8FXAH211417
5VCACL8F0AH211047	5VCACD8F6AH211091	5VCACS8F7AH211315	5VCACL8F9AH211418
5VCACL8F2AH211048	5VCACD8F8AH211111	5VCACS8F9AH211316	5VCACL8F0AH211419
5VCACL8F6AH211053	5VCACD8F5AH211132	5VCACS8F0AH211317	5VCACL8F7AH211420
5VCACL8F8AH211054	5VCACD8F7AH211133	5VCACS8F2AH211318	5VCACD8F1AH211421
5VCACD8F4AH211056	5VCACD8F9AH211134	5VCACS8F4AH211319	5VCACD8F3AH211422
5VCACD8F6AH211057	5VCACR8F6AH211153	5VCACS8F0AH211320	5VCACD8F5AH211423
5VCACD8F8AH211058	5VCACL8F7AH211174	5VCACS8F2AH211321	5VCACD8F7AH211424
5VCACD8FXAH211059	5VCACL8F9AH211175	5VCACS8F4AH211322	5VCACD8F9AH211425
5VCACD8F6AH211060	5VCACL8F0AH211176	5VCACS8F6AH211323	5VCACD8F0AH211426
5VCACD8F8AH211061	5VCACL8F2AH211177	5VCACS8F8AH211324	5VCACD8F2AH211427
5VCACD8FXAH211062	5VCACL8F4AH211178	5VCACD8F5AH211325	5VCACD8F4AH211428
5VCACD8F1AH211063	5VCACL8F6AH211179	5VCACD8F7AH211326	5VCACD8F6AH211429
5VCACD8F3AH211064	5VCACL8F2AH211180	5VCACD8F9AH211327	5VCACD8F2AH211430
5VCACD8F5AH211065	5VCACL8F4AH211181	5VCACD8F0AH211328	5VCACD8F4AH211431
5VCACD8F7AH211066	5VCACL8F6AH211182	5VCACD8F2AH211329	5VCACD8F6AH211432
5VCACD8F9AH211067	5VCACL8F8AH211183	5VCACD8F9AH211330	5VCACD8F8AH211433
5VCACD8F0AH211068	5VCA3S8F3AH211277	5VCACD8F0AH211331	5VCACD8FXAH211434
5VCACD8F0AH211071	5VCA3S8F5AH211278	5VCACD8F2AH211332	5VCACD8F1AH211435
5VCACD8F2AH211072	5VCA3S8F7AH211279	5VCA3L8F3AH211351	5VCACD8F3AH211436
5VCACD8F4AH211073	5VCA3S8F3AH211280	5VCACL8F3AH211401	5VCACD8F5AH211437
5VCACD8F8AH211075	5VCACD8G7AH211285	5VCACL8F5AH211402	5VCACD8F7AH211438
5VCACD8FXAH211076	5VCACD8F5AH211292	5VCACL8F7AH211403	5VCACD8F9AH211439
5VCACD8F1AH211077	5VCACD8F7AH211293	5VCACL8F9AH211404	5VCACD8F5AH211440

SP 3-820-001

SERVICE PROGRAM

October, 2013

5VCACD8F7AH211441	5VCA3L8F3BH211626	5VCACD8F1BH212005	5VCACD8F1BH212375
5VCACD8F9AH211442	5VCACR8F8BH211690	5VCACD8F3BH212006	5VCACD8F3BH212376
5VCACD8F0AH211443	5VCACR8FXBH211691	5VCACD8F5BH212007	5VCACD8F5BH212377
5VCACD8F2AH211444	5VCACD8F1BH211839	5VCACD8F7BH212008	5VCACD8F7BH212378
5VCACD8F4AH211445	5VCACR8F1BH211840	5VCACD8F9BH212009	5VCACD8F9BH212379
5VCACD8F6AH211446	5VCACR8F3BH211841	5VCACD8F5BH212010	5VCACD8F5BH212380
5VCACD8F8AH211447	5VCACR8F5BH211842	5VCACD8F7BH212011	5VCACD8F7BH212381
5VCACS8F4AH211448	5VCACR8F7BH211843	5VCA3L8F3BH212045	5VCACD8F9BH212382
5VCACS8F6AH211449	5VCACR8F9BH211844	5VCA3L8F1BH212046	5VCACD8F0BH212383
5VCACS8F2AH211450	5VCACR8F0BH211845	5VCA3L8F3BH212047	5VCACD8F2BH212384
5VCACS8F4AH211451	5VCACR8F2BH211846	5VCA3L8F5BH212048	5VCACD8F4BH212385
5VCACS8F6AH211452	5VCACS8F3BH211930	5VCA3L8F7BH212049	5VCACD8F6BH212386
5VCACS8F8AH211453	5VCACR8F6BH211946	5VCA3L8F3BH212050	5VCACD8F8BH212387
5VCA3L8F2AH211454	5VCA3L8F1BH211950	5VCA3L8F5BH212051	5VCACD8FXBH212388
5VCA3L8F4AH211455	5VCACS8F0BH211951	5VCACR8F2BH212060	5VCACD8F1BH212389
5VCA3L8F6AH211456	5VCACS8F2BH211952	5VCA3L8F7BH212066	5VCACD8F8BH212390
5VCACD8F0AH211457	5VCACS8F4BH211953	5VCA3D8F1BH212067	5VCACD8FXBH212391
5VCACD8F2AH211458	5VCACD8F7BH211960	5VCA3L8F0BH212071	5VCACD8F1BH212392
5VCACD8F4AH211459	5VCACD8F9BH211961	5VCA3L8F2BH212072	5VCACS8F8BH212393
5VCACD8F0AH211460	5VCACD8F0BH211962	5VCA3L8FXBH212076	5VCACS8FXBH212394
5VCACD8F2AH211461	5VCA3L8FXBH211963	5VCACS8F3BH212186	5VCACS8F1BH212395
5VCACD8F4AH211462	5VCA3L8F1BH211964	5VCACS8F5BH212187	5VCACS8F3BH212396
5VCACD8F6AH211463	5VCA3L8F3BH211965	5VCACS8F7BH212188	5VCACS8F5BH212397
5VCACR8F1AH211481	5VCA3L8F5BH211966	5VCACS8F9BH212189	5VCACS8F7BH212398
5VCACR8F3AH211482	5VCA3L8F7BH211967	5VCACS8F5BH212190	5VCACS8F9BH212399
5VCACD8F3AH211484	5VCA3L8F9BH211968	5VCACS8F7BH212191	5VCACS8F1BH212400
5VCACD8F5AH211485	5VCA3L8F0BH211969	5VCACS8F0BH212243	5VCACS8F3BH212401
5VCACD8F7AH211486	5VCA3L8F7BH211970	5VCA3L8F4BH212302	5VCACS8F5BH212402
5VCACD8F9AH211487	5VCA3L8F9BH211971	5VCACR8F3BH212343	5VCACS8F7BH212403
5VCACD8F0AH211488	5VCA3L8F0BH211972	5VCACR8F5BH212344	5VCACS8F9BH212404
5VCACD8F2AH211489	5VCA3L8F4BH211974	5VCACD8F6BH212369	5VCA3L8F3BH212405
5VCACS8F3AH211490	5VCA3L8F6BH211975	5VCACD8F2BH212370	5VCACD8FXBH212407
5VCACS8F5AH211491	5VCACD8F9BH211989	5VCACD8F4BH212371	5VCA3L8F7BH212410
5VCA3L8F3AH211513	5VCACD8F6BH212002	5VCACD8F6BH212372	5VCACR8F0BH212459
5VCACS8F3AH211537	5VCACD8F8BH212003	5VCACD8F8BH212373	5VCA3L8F0BH212460
5VCA3L8F1BH211625	5VCACD8FXBH212004	5VCACD8FXBH212374	5VCA3L8F2BH212461

SP 3-820-001 SERVICE PROGRAM

October, 2013

5VCACL8F4BH212462	5VCACS8F0BH212503	5VCACS8F7BH212613	5VCA3R8FXBH212761
5VCACL8F6BH212463	5VCACS8F2BH212504	5VCACS8F9BH212614	5VCACR8F1BH212762
5VCACL8F8BH212464	5VCACS8F4BH212505	5VCACS8F0BH212615	5VCACR8F3BH212763
5VCACL8FXBH212465	5VCACS8F6BH212506	5VCACS8F2BH212616	5VCACR8F5BH212764
5VCACL8F1BH212466	5VCACL8F0BH212507	5VCACS8F4BH212617	5VCACR8F7BH212765
5VCACL8F3BH212467	5VCACL8F2BH212508	5VCACS8F6BH212618	5VCACR8F9BH212766
5VCACL8F5BH212468	5VCACL8F4BH212509	5VCA3L8F0BH212619	5VCACR8F0BH212767
5VCACL8F7BH212469	5VCACL8F0BH212510	5VCACL8F0BH212717	5VCACR8F2BH212768
5VCACL8F3BH212470	5VCACL8F2BH212511	5VCA3D8F5BH212718	5VCACR8GXBH212798
5VCACL8F5BH212471	5VCACL8F4BH212512	5VCA3D8F7BH212719	5VCACR8G1BH212799
5VCACL8F7BH212472	5VCACL8F6BH212513	5VCACD8F3BH212720	5VCACR8G4BH212800
5VCACL8F9BH212473	5VCACL8F8BH212514	5VCACD8F5BH212721	5VCACR8F8BH212838
5VCACL8F0BH212474	5VCACD8F9BH212589	5VCACD8F7BH212722	5VCACR8FXBH212839
5VCACL8F2BH212475	5VCACD8F5BH212590	5VCACD8F9BH212723	5VCACL8FXBH212840
5VCACL8F4BH212476	5VCACD8F7BH212591	5VCACD8F0BH212724	5VCACL8F1BH212841
5VCACL8F6BH212477	5VCACD8F9BH212592	5VCACD8F2BH212725	5VCACR8F0BH212851
5VCACL8F8BH212478	5VCACD8F0BH212593	5VCACD8F4BH212726	5VCACL8F2BH212864
5VCACL8FXBH212479	5VCACD8F2BH212594	5VCACL8F3BH212727	5VCACL8F4BH212865
5VCACL8F6BH212480	5VCACD8F4BH212595	5VCACL8F5BH212728	5VCACL8F6BH212866
5VCACL8F8BH212481	5VCACD8F6BH212596	5VCACL8F7BH212729	5VCACL8F8BH212867
5VCACL8FXBH212482	5VCACD8F8BH212597	5VCACL8F3BH212730	5VCACL8FXBH212868
5VCACL8F1BH212483	5VCACD8FXBH212598	5VCACL8F5BH212731	5VCACD8F4BH212869
5VCACL8F3BH212484	5VCACD8F1BH212599	5VCACL8F7BH212732	5VCACD8F0BH212870
5VCACL8F5BH212485	5VCACD8F4BH212600	5VCACL8F9BH212733	5VCACD8F2BH212871
5VCA3L8F9BH212487	5VCACD8F6BH212601	5VCACL8F0BH212734	5VCACL8F3BH212873
5VCACR8F7BH212488	5VCACD8F8BH212602	5VCACR8F2BH212737	5VCACD8F8BH212874
5VCACD8F7BH212493	5VCACD8FXBH212603	5VCACR8F4BH212738	5VCACD8FXBH212875
5VCACD8F9BH212494	5VCACD8F1BH212604	5VCACR8F6BH212739	5VCACD8F1BH212876
5VCACS8F5BH212495	5VCACD8F3BH212605	5VCACR8F2BH212740	5VCACD8F3BH212877
5VCACS8F7BH212496	5VCACD8F5BH212606	5VCACL8F8BH212741	5VCACR8F9BH212878
5VCACS8F9BH212497	5VCACD8F7BH212607	5VCACL8FXBH212742	5VCACR8F0BH212879
5VCACS8F0BH212498	5VCACD8F9BH212608	5VCACR8F8BH212743	5VCACR8F7BH212880
5VCACS8F2BH212499	5VCACD8F0BH212609	5VCACL8FXBH212756	5VCACR8F9BH212881
5VCACS8F5BH212500	5VCACD8F7BH212610	5VCACL8F1BH212757	5VCACR8F0BH212882
5VCACS8F7BH212501	5VCACS8F3BH212611	5VCACR8FXBH212758	5VCACR8F2BH212883
5VCACS8F9BH212502	5VCACS8F5BH212612	5VCACR8F1BH212759	5VCACR8F4BH212884

SP 3-820-001
SERVICE PROGRAM

October, 2013

5VCACR8F6BH212885	5VCACS8F5BH212934	5VCA3R8F2CH213114	5VCACR8FXCH213412
5VCACR8F8BH212886	5VCACS8F7BH212935	5VCA3R8F4CH213115	5VCACR8F1CH213413
5VCACR8FXBH212887	5VCACS8F9BH212936	5VCA3R8F6CH213116	5VCACR8F3CH213414
5VCA3R8F5BH212888	5VCACD8F0BH212948	5VCACR8F8CH213117	5VCACR8F5CH213415
5VCA3R8F7BH212889	5VCACD8F2BH212949	5VCA3R8F4CH213174	5VCACR8F7CH213416
5VCA3R8F3BH212890	5VCACD8F9BH212950	5VCACR8F2CH213175	5VCACR8F9CH213417
5VCA3R8F5BH212891	5VCACD8F0BH212951	5VCA3R8F6CH213176	5VCACR8F0CH213418
5VCA3R8F7BH212892	5VCACD8F2BH212952	5VCACR8F8CH213177	5VCACR8F2CH213419
5VCA3R8F9BH212893	5VCACD8F4BH212953	5VCA3R8F4CH213178	5VCACR8F9CH213420
5VCA3R8F0BH212894	5VCACD8F6BH212954	5VCACR8FXCH213179	5VCACR8F0CH213421
5VCA3R8F2BH212895	5VCACD8F8BH212955	5VCA3R8F1CH213180	5VCACR8F2CH213422
5VCA3R8F4BH212896	5VCACR8F0BH212980	5VCACR8F8CH213181	5VCACR8F4CH213423
5VCA3R8F6BH212897	5VCACD8F0BH212996	5VCA3R8F9CH213182	5VCACR8F6CH213424
5VCA3R8F8BH212898	5VCACR8F7BH213010	5VCACR8F5CH213183	5VCACR8F8CH213425
5VCA3R8FXBH212899	5VCACR8F6BH213020	5VCACD8G2CH213184	5VCACR8FXCH213426
5VCA3R8F2BH212900	5VCA3R8F1BH213021	5VCACD8G4CH213185	5VCACR8F1CH213427
5VCA3R8F4BH212901	5VCA3R8F3BH213022	5VCACD8G6CH213186	5VCACR8F3CH213428
5VCA3R8F6BH212902	5VCA3R8F5BH213023	5VCACR8F3CH213187	5VCACD8F4CH213439
5VCA3R8F8BH212903	5VCA3R8F7BH213024	5VCACD8G2CH213188	5VCA3R8F3CH213507
5VCA3R8FXBH212904	5VCACS8FXBH213030	5VCACD8G6CH213189	5VCACR8G6CH213576
5VCA3R8F1BH212905	5VCACS8F1BH213031	5VCACR8F5CH213189	5VCACS8F4CH213610
5VCA3R8F3BH212906	5VCACR8F2BH213032	5VCACD8G2CH213190	5VCACS8F6CH213611
5VCA3R8F5BH212907	5VCA3R8F8BH213033	5VCACR8F3CH213199	5VCACS8F8CH213612
5VCA3R8F7BH212908	5VCA3R8FXBH213034	5VCACD8G2CH213200	5VCACS8FXCH213613
5VCA3R8F9BH212909	5VCA3R8F1BH213035	5VCACR8F6CH213201	5VCACS8F1CH213614
5VCA3R8F5BH212910	5VCA3R8F3BH213036	5VCACD8F8CH213204	5VCACS8F3CH213615
5VCA3R8F7BH212911	5VCA3R8F5BH213037	5VCA3R8F7CH213204	5VCACS8F5CH213616
5VCA3R8F9BH212912	5VCACD8FXBH213038	5VCACD8F8CH213279	5VCACS8F7CH213617
5VCA3R8F0BH212913	5VCACR8F5BH213039	5VCA3R8F8CH213280	5VCACS8F9CH213618
5VCA3R8F2BH212914	5VCA3R8F3BH213041	5VCA3R8F8CH213281	5VCACS8F0CH213619
5VCA3R8F4BH212915	5VCACR8F5BH213042	5VCA3R8F7CH213403	5VCACS8F7CH213620
5VCA3R8F6BH212916	5VCACR8F7BH213043	5VCACR8FXCH213407	5VCACS8F9CH213621
5VCA3R8F8BH212917	5VCA3R8F2BH213044	5VCACR8FXCH213409	5VCACS8F0CH213622
5VCACS8F7BH212918	5VCA3R8F4BH213045	5VCACR8F6CH213410	5VCACS8F2CH213623
5VCACS8F9BH212919	5VCA3R8FXBH213053	5VCACR8F8CH213411	5VCACS8F4CH213624
5VCACR8F4BH212920			5VCACS8F6CH213625

SP 3-820-001 SERVICE PROGRAM

October, 2013

5VCACS8F8CH213626	5VCACR8F7CH213805	5VACL8F0CH214002	5VCACR8F3CH214255
5VCACS8FXCH213627	5VCACR8F9CH213806	5VACL8F2CH214003	5VCACR8F5CH214256
5VCACS8F1CH213628	5VCACR8F0CH213807	5VACL8F4CH214004	5VCACR8F7CH214257
5VCACS8F3CH213629	5VCACR8F2CH213808	5VACL8F6CH214005	5VCACR8F9CH214258
5VCACS8FXCH213630	5VCACR8F4CH213809	5VACL8F8CH214006	5VACL8F0CH214260
5VCACS8F1CH213631	5VCACR8F0CH213810	5VACL8FXCH214007	5VCACR8G8CH214261
5VACL8F8CH213633	5VCACR8F2CH213811	5VACL8F1CH214008	5VCACS8F0CH214284
5VACL8FXCH213634	5VCACR8F4CH213812	5VACL8F3CH214009	5VCACD8F5CH214292
5VACL8F1CH213635	5VCACR8F4CH213910	5VACL8FXCH214010	5VCACD8F7CH214293
5VACL8F3CH213636	5VCACR8F6CH213911	5VACL8F1CH214011	5VCACD8F9CH214294
5VACL8F5CH213637	5VCACR8F8CH213912	5VCACR8F0CH214021	5VCACD8F0CH214295
5VCACR8F9CH213692	5VCACR8FXCH213913	5VCACR8F2CH214022	5VCACD8F2CH214296
5VCACR8F0CH213693	5VCACR8F1CH213914	5VACL8F1CH214087	5VCACD8F4CH214297
5VCACR8F2CH213694	5VCA3D8F0CH213955	5VACL8F3CH214088	5VCACD8F6CH214298
5VCACR8F9CH213742	5VCA3D8F2CH213956	5VCACR8F1CH214089	5VCACD8F6CH214303
5VCACR8F0CH213743	5VCACR8G7CH213957	5VCACR8F8CH214090	5VACL8F5CH214318
5VCACR8F2CH213744	5VCACD8F6CH213958	5VCACD8G5CH214091	5VACL8F2CH214339
5VCACR8F4CH213745	5VCACD8F8CH213959	5VACL8F5CH214092	5VCACR8F5CH214340
5VCACR8F6CH213746	5VCACD8F4CH213960	5VACL8F7CH214093	5VCACR8F7CH214341
5VCACD8F8CH213749	5VCACD8F6CH213961	5VACL8F9CH214094	5VCACR8F9CH214342
5VCACD8F1CH213771	5VCACR8G2CH213963	5VCACR8F7CH214095	5VCACR8F0CH214343
5VCACS8F8CH213772	5VCACR8F0CH213967	5VCACR8F9CH214096	5VCACR8F2CH214344
5VCACS8FXCH213773	5VCACR8F0CH213970	5VCACR8F0CH214097	5VCACR8F4CH214345
5VCACR8F9CH213790	5VCACR8F2CH213971	5VACL8F4CH214102	5VCACR8F6CH214346
5VCACR8F0CH213791	5VACL8F8CH213972	5VCACD8FXCH214224	5VCACR8F8CH214347
5VCACR8F2CH213792	5VACL8FXCH213973	5VCACD8F1CH214225	5VCACR8FXCH214348
5VCACR8F4CH213793	5VACL8F1CH213974	5VCACD8F3CH214226	5VCACR8F1CH214349
5VCACR8F6CH213794	5VACL8F3CH213975	5VCACR8F9CH214227	5VCACR8F8CH214350
5VCACR8F8CH213795	5VCACR8F4CH213986	5VCACR8F0CH214228	5VCACR8FXCH214351
5VCACR8FXCH213796	5VCACR8F6CH213987	5VCACR8F2CH214229	5VCACD8F8CH214352
5VCACR8F1CH213797	5VCACR8F8CH213988	5VCACR8F8CH214249	5VCACS8F4CH214353
5VCACR8F3CH213798	5VCACR8FXCH213989	5VCACR8F4CH214250	5VCACS8F5CH214376
5VCACR8F5CH213799	5VACL8FXCH213990	5VCACR8F6CH214251	5VCACS8F7CH214377
5VCACR8F1CH213802	5VACL8F1CH213991	5VCACR8F8CH214252	5VCACD8G0CH214404
5VCACR8F3CH213803	5VACL8F7CH214000	5VCACR8FXCH214253	5VCACR8G6CH214405
5VCACR8F5CH213804	5VACL8F9CH214001	5VCACR8F1CH214254	5VCACR8G8CH214406

SP 3-820-001

SERVICE PROGRAM

October, 2013

5VACL8F6CH214411	5VCACA8F5DH214714	5VACL8F1DH214785	5VCACS8F0DH215159
5VACL8F8CH214412	5VCACA8F7DH214715	5VACL8F3DH214786	5VCACR8F6DH215160
5VACL8F1CH214414	5VCACA8F9DH214716	5VACL8F5DH214787	5VCACR8F8DH215161
5VACL8F1CH214445	5VCACA8F0DH214717	5VACL8F7DH214788	5VCACD8F6DH215162
5VACL8F3CH214446	5VCACA8F2DH214718	5VCACD8F7DH214845	5VCACD8F8DH215163
5VCACS8F2CH214447	5VCACA8F4DH214719	5VCACD8F7DH214859	5VCACS8F3DH215169
5VCACS8F4CH214448	5VCACR8G1CH214733	5VCACD8F3DH214860	5VCACS8FXDH215170
5VCACS8F6CH214449	5VCACR8F4CH214734	5VCACD8F5DH214861	5VCACR8F5DH215182
5VCACS8F2CH214450	5VCACR8F6CH214735	5VCACD8F7DH214862	5VCACR8F7DH215183
5VCACR8F4CH214555	5VCACR8F8CH214736	5VCACD8F9DH214863	5VCACR8F9DH215184
5VCACR8F6CH214556	5VCACR8FXCH214737	5VCACD8F0DH214864	5VCA3R8F0DH215185
5VCACR8F8CH214557	5VCACR8F1CH214738	5VCACD8F2DH214865	5VACL8F4DH215204
5VCACR8FXCH214558	5VCACR8F3CH214739	5VCACD8F4DH214866	5VACL8F6DH215205
5VCACR8F1CH214559	5VCACR8FXCH214740	5VCACD8F9DH214877	5VCACD8F0DH215206
5VCACR8F8CH214560	5VCACR8F1CH214741	5VACL8F3DH214903	5VCACD8F2DH215207
5VCACR8F0CH214567	5VCACR8F3CH214742	5VCACD8G7DH214904	5VCACR8F6DH215210
5VCACR8G8CH214583	5VCACR8F5CH214743	5VCACD8G9DH214905	5VACL8F2DH215220
5VCACD8G8CH214585	5VCACR8F7CH214744	5VCACD8F3CH214906	5VCACD8F3DH215233
5VACL8F8CH214586	5VCACR8F9CH214745	5VCACD8F5CH214907	5VCACD8F5DH215234
5VACL8FXCH214587	5VCACR8F0CH214746	5VCACD8F0DH214914	5VACL8FXDH215241
5VCACR8F8CH214588	5VCACR8F2CH214747	5VCACD8F2DH214915	5VACL8F1DH215242
5VCACR8FXCH214589	5VCACR8F4CH214748	5VCACD8F3DH214938	5VACL8F3DH215243
5VCACD8F4CH214591	5VACL8F1DH214771	5VACL8F6DH214944	5VACL8F5DH215244
5VACL8F4CH214696	5VACL8F3DH214772	5VACL8F8DH214945	5VACL8F7DH215245
5VCACR8F0CH214701	5VACL8F5DH214773	5VACL8F5DH214952	5VCACD8F1DH215246
5VACL8F6CH214702	5VACL8F7DH214774	5VACL8F7DH214953	5VCACD8F3DH215247
5VACL8F8CH214703	5VACL8F9DH214775	5VACL8F3DH214965	5VCACD8F5DH215248
5VACL8FXCH214704	5VACL8F0DH214776	5VCACS8FXDH215038	5VCACD8F7DH215249
5VACL8F1CH214705	5VACL8F2DH214777	5VCACS8F1DH215039	5VCACD8F3DH215250
5VACL8F3CH214706	5VACL8F4DH214778	5VCACS8F8DH215040	5VCACS8F0DH215257
5VACL8F5CH214707	5VACL8F6DH214779	5VCACR8F0DH215042	5VACL8F0DH215264
5V4A4D8F0CH214709	5VACL8F2DH214780	5VCACR8G1DH215043	5VCACS8F8DH215281
5V4A4D8F7CH214710	5VACL8F4DH214781	5VACL8F3DH215047	5VACL8F7DH215293
5V4A4D8F9CH214711	5VACL8F6DH214782	5VACL8F5DH215048	5VCACD8FXDH215309
5VCACR8G4CH214712	5VACL8F8DH214783	5VCACR8F5DH215134	5VCACD8F6DH215310
5VCACA8F3DH214713	5VACL8FXDH214784	5VCACD8G1DH215157	5VCACR8F4DH215349

SP 3-820-001

SERVICE PROGRAM

October, 2013

5VCACD8F7DH215350

5VCACD8F9DH215351

5VCACR8F7DH215409

5VCACR8F3DH215410

5VCACR8F5DH215411