



**NUMBER:** 08-067-13

**GROUP:** Electrical

**DATE:** September 04, 2013

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.*

**THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 13-063. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.**

**SUBJECT:**

No Start Condition Due To Totally Integrated Power Module (TIPM)

**OVERVIEW:**

This bulletin describes a no start condition due to the TIPM.

**MODELS:**

2013 (JK) Wrangler

**NOTE:** This bulletin applies to vehicles built on or after May 29, 2013 (MDH 0529XX) and on or before June 06, 2013 (MDH 0606XX).

**SYMPTOM/CONDITION:**

The customer may experience a no start condition.

**DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	68163903AC	TIPM Module (TIPM7)

**REPAIR PROCEDURE:**

1. Remove the TIPM. Refer to the detailed repair procedures available in: DealerConnect> TechCONNECT under: 08 - Electrical> 8E - Electronic Control Modules> MODULE, Totally Integrated Power (TIPM)> Removal.
2. Install the new TIPM. Refer to the detailed repair procedures available in: DealerConnect> TechCONNECT under: 08 - Electrical> 8E - Electronic Control Modules> MODULE, Totally Integrated Power (TIPM)> Installation.
3. Using WiTech, clear fault codes.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

<b>Labor Operation No:</b>	<b>Description</b>	<b>Skill Category</b>	<b>Amount</b>
08-89-01-94	Replace TIPM (2 - Skilled)	6 - Electrical and Body Systems	0.3 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------