

Fuel hose under engine cover leaky

Topic number	LI47.25-N-057148
Version	1
Design group	47.25 Lines, hoses
Date	09-16-2013
Validity	MODEL 906 with OM651
Reason for change	Distribution extended
Reason for block	

Complaint:

Fuel hose under engine cover leaky.

Cause:

Fuel hose chafes on engine cover.

Remedy:

Replace fuel hose and connect to other line with hose bracket (see attachment).

Attachments	
File	Designation
1.jpg	Hose bracket on fuel hose.

Symptoms
Power generation / Fuel system / Fuel system odor / Odor
Power generation / Fuel system / Fuel system leaks / System leaks

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other make part
A 651 070 08 81			Fuel hose	1		X	
A 123 995 02 65			Clamp	1		X	
A 000 995 66 65			Hose bracket	1		X	

Validity		
Vehicle	Engine	Transmission
906.111	651	*
906.113	651	*

XENTRY

906.131	651	*
906.132	651	*
906.133	651	*
906.134	651	*
906.135	651	*
906.136	651	*
906.153	651	*
906.155	651	*
906.211	651	*
906.213	651	*
906.231	651	*
906.233	651	*
906.234	651	*
906.235	651	*
906.236	651	*
906.253	651	*
906.255	651	*
906.611	651	*
906.613	651	*
906.631	651	*
906.633	651	*
906.635	651	*
906.637	651	*
906.653	651	*
906.655	651	*
906.657	651	*
906.733	651	*
906.735	651	*

Attachments

1.jpg:

