

SB-10054016-8882

Repair Notice

613-1

Section

Instrumentation

Description

Model 587 Dash Cluster Dropout

Release Date

11/11/2013

Introduction

Peterbilt Motors has determined that certain Model 587 vehicles built with 2013 engines through 05/23/13 may experience the dash cluster going dark at startup. This issue may result in an inability to read the instrument cluster, which includes the speedometer, tachometer, coolant, DEF, fuel, oil, primary air and secondary air gauges.

Expiration Date: November 11, 2014

Resolution

Flash the vehicle CECU with the latest CECU Software using ESA.

Warranty

Peterbilt will reimburse the dealer for 0.3 hours to re-flash the vehicle CECU with latest CECU software.

Submit quick claim **613-1** for this repair.

Parts

No parts are associated with this campaign

Labor

Peterbilt will reimburse the dealer for 0.3 hours of labor to re-flash the vehicle CECU using ESA.

Procedure

Flash the vehicle CECU with the latest CECU Software using ESA.

Attachments

[613-1 Chassis List](#)

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2013 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).