

View Message

Sent on 07 30 2013 **Expires on** 08 12 2013
From Parts and Service Division
Subject Request for Parts: 2010-2012 Odyssey, Pilot & Ridgeline Engine B-Cap Oil Leak

To: All Honda Service Managers/Advisors
From: Technical Research & Support Group
RE: 2010-2012 Odyssey, Pilot & Ridgeline V6 Engine B-Cap Side Bolt Oil Leak

Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

Background

American Honda (AHM) is investigating certain 2010-2012 Odysseys, Pilots & Ridgelines with a complaint of oil leak at the B-Cap side bolts. To fully understand the cause of this occurrence, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. VINs starting with 5FN or 5FP.
2. Vehicle must be under the Powertrain Warranty (5 years or 60,000 miles)
3. Leak must be from the V6 B-Cap Side Bolts.
4. Click [here](#) to view the sample picture of the oil leak.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.