

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM  
FOR SEPTEMBER 2013**

44202 2009 -2013 F650/750 Vehicles with Hydraulic Brakes □ Invalid DTC (diagnostic trouble code) set in the GEM (Generic Electronic Module).

During diagnostics a C1268 (Hydromax Motor Relay # 1 Circuit Failure) DTC may be encountered from the GEM when pulling codes or after configuring a new GEM. Because Hydromax is no longer used this DTC should be ignored. There is currently no method to configure the GEM to not set this DTC.