



Service Bulletin

PRELIMINARY INFORMATION

Subject: Instrument Panel Brightness too Low

Models: 2014 Chevrolet Corvette
Condition/Concern

Some customers may comment that the instrument panel brightness is too low during twilight or dusk and cannot be adjusted brighter.

Recommendation/Instructions

Updated software calibrations have been released to address this condition.

Reprogram the following modules individually using the Service Programming System (SPS) and ensure all necessary set-ups and USB updates are completed using the latest calibrations available on TIS2WEB. Refer to the SPS procedures in SI.

- BCM
- HVAC
- Radio
- IPC

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2880178*	BCM, HVAC, Radio and IPC Programming	0.7 hr
*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		