



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - ABS/Traction Control Indicators On No Communication With The EBCM

Models: 2014 Buick Verano

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment that the ABS/Traction Control Indicators are on in the IPC.

During initial scan for diagnostic codes you may find that there is a U0415 stored and notice that you cannot communicate with the K17 Electronic Brake Control Module (EBCM).

There is currently an issue with GDS2 which is not allowing the Scan Tool to communicate with the K17 Electronic Brake Control Module EBCM.

Recommendation/Instructions

For a current work around, build the vehicle as a 2013 Model Year Buick Verano. This will allow the Technician to communicate with the K17 Electronic Brake Control Module (EBCM) and address any current DTCs that might be stored.

Engineering has been made aware of this issue and is working to correct the concern.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.