
**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR NOVEMBER 2013**

44308 2008-2013 Edge/MKX Power Steering Fluid Leak From Pressure Line Banjo Fitting

Some 2008 to 2013 Edge and MKX vehicles may exhibit power steering fluid leak at the banjo fitting attaching the pressure hose to the steering gear. Please use leak diagnostics from Workshop Manual, Section 211-00. If the leak is from the banjo fitting, please install only a new banjo bolt and seals using the 8E5Z-3A705-A seal kit.
