

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR DECEMBER 2013**

44339 DTC P1A18, P1A19, P0AEE, P0BCD When Using Engine Block Heater - Under Investigation

Some 2013-2014 C-MAX, Fusion and MKZ Hybrid/Energi vehicles may illuminate the wrench lamp (Hybrids) or the Service Engine Soon lamp (Energi) when using the engine block heater, with diagnostic trouble codes P1A18, P1A19, P0AEE or P0BCD in continuous memory of the SOBDM-C. The lamps will turn off within no more than three drive cycles after the engine block heater is unplugged. Engineering is currently investigating this condition and will be releasing an updated calibration to resolve this concern. Monitor OASIS for updates.