

ONLINE AUTOMOTIVE SERVICE INFORMATION
FOR OCTOBER 2013

SB-10054968-8008

44237 2010-2013 Mustang - Built On Or Before 10/31/2012 - Outside Door Handle Needs To Be Pulled More Than One Time To Open Door(s)

Some 2010-2013 Mustang vehicles built on or before 10/31/2012 may exhibit a customer complaint of outside door handle needs to be pulled more than one time to open door(s). Perform the Door Handle to Latch Rod Adjustment procedure in the Workshop Manual (WSM), section 501-14 under the General Procedures to correct this condition. Use available service labor times.