

Condition

Abnormal oil colour and water vapour in oil filler cap during PDI

Technical Background

Additives used during manufacture can result in this phenomena

Production Solution

None

Service

We are receiving a number of DISS tickets for abnormal oil colour and water vapour in oil filler cap during PDI

*This is normal at PDI when an engine has been run with a leak detection additive in it from the factory. There are no issues with the engine oil

Emulsification is normal and will burn off in time